

L Number	Hits	Search Text	DB	Time stamp
1	1911	quartz with metal with (heat\$3 or shrink near fit\$4)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 13:39
2	9	quartz with metal with (shrink adjfit\$4)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 14:13
10	0	((gravity adj sensor) with quartz with metal).ab.	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:40
11	0	((gravity adj sensor) with quartz with metal)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:40
14	0	((gravity adj sensor).ab.) and (quartz with metal)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:46
15	0	((gravity adj sensor).ab.) and quartz and metal	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:46
16	2	((gravity adj sensor).ab.) and quartz	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:46
17	0	((gravity adj sensor).ab.) and quartz and (proof near mass)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:50
18	2	((gravity adj sensor).ab.) and quartz	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:49
19	9	((gravity adj sensor).ab.) and glass	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:49
20	9	((((gravity adj sensor).ab.) and glass) not (((gravity adj sensor).ab.) and quartz)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:49
21	0	((gravity adj sensor).ab.) and (proof near mass)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:50
22	20	((gravity adj sensor).ab.) and mass	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:50
23	18	((((gravity adj sensor).ab.) and mass) not (((((gravity adj sensor).ab.) and glass) not (((gravity adj sensor).ab.) and quartz))	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 15:51

26	12	(metal near mass) with quartz	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/17 16:12
----	----	-------------------------------	---	---------------------